

NOTES	
1	Excess joints cut back at gates C to D and gates D to E.
2	Original shape badly damaged.
3	Unfinished cutting of corner of shaft.
4	Access to chamber is generally blocked by debris in the shaft.



